

[← Back to search](#)

WIN 10 Upgrade Options

Answer #39423 | Access: Everyone

CEREC - Windows 10 Upgrade for Omnicam

Applies to: CEREC AC Omnicam

Dentsply Sirona is offering upgrade options for existing CEREC Omnicam owners to transition to Windows 10.

An optional hardware upgrade to existing CEREC AC with Omnicam units is required in order to run CEREC Software 5.1. Users can choose between a complete **PC** upgrade or a specific Performance Package depending on the existing hardware status for the device. Customers can opt to continue using their existing computer and Windows 7, but will not be able to run CEREC 5.X software.

Acquisition units with **PC** status 2.2.1-2.2.7* will be required to purchase a **PC** upgrade. **PC** status of 3.2.1-4.4.1 will have Performance Package kits predefined for these machines that include a solid-state drive and RAM upgrade kit.

See FAQ [39424](#) for steps to check your **PC** Hardware status.

CEREC Club members enjoy reduced prices on all kits and **PC** when compared to MSRP.

To upgrade from hardware versions 2.2.1 to 2.2.7, the following material number must be ordered for an Upgrade **PC**:

Sirona Part #	Patterson SAP Part #	Description	Price	Club Status
6726900	50365968	Omnicam PC Upgrade Win10	\$4359 + \$0 Software	CEREC Club
6726892	50364851	Omnicam PC Upgrade Win10	\$5459 + \$5000 Software	Non-Club

To upgrade from hardware versions 3.2.1 to 4.4.1, the following material numbers must be ordered for the upgrade packages to match the hardware version:

Sirona Part #	Patterson SAP Part #	Description	Price	Club Status
6735471	50364984	Performance Package V3.2.x / V3.4.x	\$1000 + \$0 Software	CEREC Club
6735489	50364992	Performance Package V4.2.1 / V4.4.1	\$1000 + \$0 Software	CEREC Club
6727411	50364877	Performance Package V3.2.x / V3.4.x	\$1600 + \$5000 Software	Non-Club
6727429	50364885	Performance Package V4.2.1 / V4.4.1	\$1600 + \$5000 Software	Non-Club

To order software for non-club members:

Patterson SAP Part #	Description	Price	Club Status
50364844	CEREC SW 5.1 SW	\$5,000	Non-Club

*Note: hardware status 2.2.7 was previously listed as a Performance Package upgrade in some printed materials. This **PC** status was reclassified prior to the launch of this program as a **PC** upgrade due to further testing.

Printed Copies of this document are considered uncontrolled.

39423.Rev001 10.17.2019